

FIGURE 4
MID-DEPTH GROUNDWATER
RESULTS (JANUARY 2013)
 HEGELER ZINC SUPERFUND SITE
 DANVILLE, ILLINOIS




FIGURE 3
MID-DEPTH POTENTIOMETRIC
SURFACE (FEBRUARY 2013)
 HEGELER ZINC SUPERFUND SITE
 DANVILLE, ILLINOIS